

$$g_{d,quad} = \mu C_{ox} \frac{W}{L} (V_{GS} - V_T - V_{DS})$$